# **EOSDIS Core System Project**

# Interim Release One (Ir1) Version Description Document (VDD) for the ECS Project

Subject to government approval and not intended for general distribution.

Version 1.04.04

August 14, 1996

Hughes Information Technology Systems
Upper Marlboro, Maryland

# Interim Release One (Ir1) Version Description Document (VDD) for the ECS Project

Version 1.04.04

August 14, 1996

Prepared Under Contract NAS5-60000

#### **SUBMITTED BY**

Robert E. Clinard /s/ 8/20/96

Robert E. Clinard, ECS CCB Chairman Date
EOSDIS Core System Project

**Hughes Information Technology Systems** 

Upper Marlboro, Maryland

This page intentionally left blank.

#### **Preface**

This document describes the configuration of Version 1.04.04 and the delta changes since the release of Version 1.04.02 of Interim Release One (Ir1). This attachment reflects updates to software released as of August 14, 1996. It is not a formal deliverable and does not require Government approval. However, it has been placed under configuration control by the ECS CCB. Changes to this document shall be made by document change notice (DCN) or by complete revision.

Any questions regarding distribution should be addressed to:

Data Management Office The ECS Project Office Hughes Information Technology Systems 1616 McCormick Dr. Upper Marlboro, MD 20774-5372 This page intentionally left blank.

#### **Abstract**

This document describes the delivery contents of Ir1 (also referred to as *the product*) components including Commercial Off-The-Shelf (COTS) hardware and software (*Ir1 COTS*), Version 1.00 of custom Ir1 ECS software (*Ir1 Software*) and accompanying documentation.

The purpose of this document is to describe the contents of the Ir1 delivery. It briefly describes the capabilities of the product, provides an inventory of the delivery, lists unresolved problems, and addresses issues such as special operating instructions, system limitations, and disclaimer notices for public domain software used in the product.

This document describes the configuration of Version 1.04.04 and the delta changes since the release of Version 1.04.02 of Interim Release One (Ir1). This attachment reflects updates to software released as of August 14, 1996.

*Keywords:* version, description, release, software, Ir1, hardware, deliver, CCB, problems, instructions, TRMM, SSI&T, inventory, patch

# **Change Information Page**

	List of Effect	ive Sections			
Section	Number	<b>Issue</b> Version 1.04.04			
4	.2				
5	.2	Version	1.04.04		
Apper		Version			
, про		. 0101011			
	Documer	nt History			
Document Number	Status/Issue	Publication Date	CCR Number		
814-RD-004-001	Original, Version 1.00	January 3, 1996	96-0044		
814-RD-004-002	Version 1.01	January 31, 1996	96-0107		
814-RD-004-003	Version 1.02	February 9, 1996	96-0108		
814-RD-004-004	Version 1.03	April 10, 1996	96-0370		
814-RD-004-005	Version 1.03	May 7, 1996	96-0370A		
814-RD-004-006	Version 1.04	May 22, 1996	96-0523		
814-RD-004-007 Version 1.04.01 June 11, 1996 96-0624					

96-0681

96-0886

Version 1.04.02

Version 1.04.04

814-RD-004-008

814-RD-004-009

July 12, 1996

August 14, 1996

# **Contents**

### **Preface**

#### **Abstract**

4.2	COTS Software Listing	1
5.2	Ir1 Non-Conformance Reports (Closed Status)	4
	Appendix F. Archive Tapes	5
	Tables	
4.2-1	COTS Software Report (Ir1 VDD Version 1.04.04)	2

## 4.2 COTS Software Listing

Table 4.2-1 provides a detailed list of the deployed patches for SGI (Indigo2 system) with an Exabyte tape stacker (SCSI) attached. The COTS software is scheduled for delivery to GSFC for Ir1.

1

Table 4.2-1. COTS Software Report (Ir1 VDD Version 1.04.04)

SITE: GSFC, Greenbelt MD SUBSY			SUBSYSTEM: N/A	BSYSTEM: N/A						
ECSNAM	MFR/DEV	DESC	RIPTION	MOD/	VER	File(s) Location	Hardware Platform	PARENT_EC N	SERIAL_NU M	QTY/LI C
N/A	Silicon Graphics, Inc	corr read	00736 - Patch ects problems with ing variable length records	IRIX	5.3	**	All SGI systems (except Challeng e and Onyx), Adtron SDDS PC	N/A	N/A	1
N/A	Silicon Graphics, Inc	corr	0783 - Patch ects problems with yte devices	IRIX	5.3	** replaces tpsc driver	All 5.3 platform s	N/A	N/A	1
N/A	Silicon Graphics, Inc	corr scri	0852 - Patch ects the MAKEDEV pt so that it will d the correct ce.	IRIX	3.5.3	**	Challeng e and Onyx, includin g Challeng eS	N/A	N/A	1
N/A	Silicon Graphics, Inc		01157 - Patch adds ort to the CDE GUI.	IRIX	5.3	* *	IP22 systems	N/A	N/A	1

<sup>\*\*</sup> Install like any other Silicon Graphics software products

2 814-RD-004-009

SITE: LARC, L	angley	SUBSYSTEM: N/A	SUBSYSTEM: N/A					
ECSNAM	MFR/DEV	DESCRIPTION	MOD/VER	File(s) Location	Hardware Platform	PARENT_EC N	SERIAL_NU M	QTY/LI C
N/A	Silicon Graphics, Inc	SG0000736 - Patch corrects problems with reading variable length tape records	IRIX 5.3	**	All SGI systems (except Challeng e and Onyx), Adtron SDDS PC	N/A	N/A	1
N/A	Silicon Graphics, Inc	SG000783 - Patch corrects problems with exabyte devices	IRIX 5.3	** replaces tpsc driver	All 5.3 platform s	N/A	N/A	1
N/A	Silicon Graphics, Inc	SG000852 - Patch corrects the MAKEDEV script so that it will build the correct device.	IRIX 5.3	**	Challeng e and Onyx, includin g Challeng eS	N/A	N/A	1
N/A	Silicon Graphics, Inc	SG0001157 - Patch adds support to the CDE GUI.	IRIX 5.3	**	IP22 systems	N/A	N/A	1

<sup>\*\*</sup> Install like any other Silicon Graphics software products

3 814-RD-004-009

#### 5.2 Ir1 Non-Conformance Reports (Closed Status)

NCRs closed as of August 14, 1996

Problem Id: ECSed02560

Severity: 3

Title: System crashed while accessing Exabyte drives

Problem: The SGI Indigo2 (ICL1SGIGSFC) crashed with the error - KERNAL

FAULT -SCSI BUS RESET. This happened while the Sys Admin (Jeff Armstrong) was accessing the Exabyte tape drive. Steve (the SGI Tech) was in the building at the time of the crash, so he took a look at the crashlog. He

suggested that four patches (736, 852, 783, 1157) be loaded.

Since the machines were not currently being used to support the planned TSDIS I/F testing, the patches were applied as a corrective measure. The system is now in a test configuration mode. This occured on 7/19/96. Since

that time, there has been no reocurrence of the problem.

It should also be noted that this problem had previously intermittently occured. Rebooting was the workaround solution to solving the problem. Since it was intermittent and it was thought that the cable lengths had some

effect on the problem, this was not previously submitted as an NCR.

Resolution: Install patches for problems encountered, all patches should **not** be installed

by default.

# **Appendix F. Archive Tapes**

The following magnetic tape is used to archive the delivered baseline configuration of the developed software.

#### 904-PR-021-001

Label: IR1\_1.04.04\_gsfc.scsi Distribution Date: August 7, 1996 >>> 5.0gbyte format (high density) <<<

IR1\_1.04.04\_gsfc\_scsi.tar

Command to dump tape: tar xvf ##
where ## = your tape device
Command to untar tar file: tar xvf file.tar
where file.tar = name you give tar file